# Salisbury Hazard Risk Category PPE Chart

HAZARD RISK CATEGORY 1

Required minimum Arc Rating of PPE 4CAL/CM²

- Arc-Rated Long-Sleeve Shirt and Pants or Arc-Rated Coverall
- Arc-Rated Face shield or Arc Flash Suit hood
- Arc-Rated Jacket, Parka,or Rainwear (AN)
- Hard Hat
- Safety Glasses or Safety Goggles (SR)
- Hearing Protection (Ear Canal Inserts)
- Heavy Duty Leather Gloves*
- Leather work Shoes (AN)

HAZARD RISK CATEGORY 2

Required minimum Arc Rating of PPE 8CAL/CM²

- Arc-Rated Long-Sleeve Shirt and Pants or Arc-Rated Coverall
- Arc Flash Suit Hood or Arc-Rated Face shield and Arc-Rated Balaclava
- Arc-Rated Jacket, Parka, or Rainwear (AN)
- Hard Hat
- Safety Glasses or Safety Goggles (SR)
- Hearing Protection (Ear Canal Inserts)
- Heavy Duty Leather Gloves*
- Leather work Shoes

HAZARD RISK CATEGORY 3

Required minimum Arc Rating of PPE 25CAL/CM²

- Arc-Rated Long-Sleeve Shirt (AR)
- Arc-Rated Pants (AR)
- Arc-Rated Coverall (AR)
- Arc-Rated Arc Flash Suit Jacket (AR)
- Arc-Rated Arc Flash Suit Pants (AR)
- Arc-Rated Arc Flash Suit Hood
- Arc-Rated Gloves or Rubber Insulating Gloves with Leather Protectors (SR)
- Arc-Rated Jacket, Parka, Rainwear or Hard Hat Liner (AN)
- Hard Hat
- Safety Glasses or Safety Goggles (SR)
- Hearing Protection (Ear Canal Inserts)
- Leather Work Shoes

HAZARD RISK CATEGORY 4

Required minimum Arc Rating of PPE 40CAL/CM²

- Arc-Rated Long-Sleeve Shirt (AR)
- Arc-Rated Pants (AR)
- Arc-Rated Coverall (AR)
- Arc-Rated Arc Flash Suit Jacket (AR)
- Arc-Rated Arc Flash Suit Pants (AR)
- Arc-Rated Arc Flash Suit Hood
- Arc-Rated Gloves or Rubber Insulating Gloves with Leather Protectors (SR)
- Arc-Rated Jacket, Parka, Rainwear or Hard Hat Liner (AN)
- Hard Hat
- Safety Glasses or Safety Goggles (SR)
- Hearing Protection (Ear Canal Inserts)
- Leather Work Shoes

⚠ NOTE:

ALWAYS WEAR VOLTAGE RATED RUBBER GLOVES WITH PROTECTORS WHEN WORKING ON VOLTAGES OPERATING AT 50V OR MORE.

*Leather Gloves made entirely of leather with a minimum thickness of .03, are unlined or lined with nonflammable non-melting fabrics.

AN = As Needed (optional)
AR = As Required
SR = Selection Required

SALISBURY PRO-WEAR ARC FLASH PROTECTION

SALISBURY
by Honeywell